



# 1010a IAQ Meter

## APPLICATIONS

- Check ambient CO and CO<sub>2</sub> levels in work and living spaces
- Monitor results of air control systems
- Ambient air temperature and Humidity
- Test dew point and wet bulb humidity



## FEATURES & BENEFITS

- Calculate percent outside air to maintain acceptable CO<sub>2</sub> levels in buildings and work spaces
- Measure and display Carbon Dioxide (CO<sub>2</sub>) and Carbon Monoxide
- Measure ambient air temperature
- Measure relative humidity, dew point and wet bulb
- Log up to 4,000 readings in 1 second to 23 hour 59 minute intervals
- Download to a computer using the A368 USB cable

### MEASUREMENTS

|                         |                            |
|-------------------------|----------------------------|
| CO <sub>2</sub> .....   | 0 to 5000ppm               |
| Temperature .....       | -4 to 140°F (-20 to 60°C)  |
| Relative Humidity ..... | 5 to 95%                   |
| Dew Point .....         | -47 to 135°F (-44 to 57°C) |
| Wet Bulb .....          | 3 to 135°F (-16 to 57°C)   |
| CO .....                | 0 to 500ppm                |

### RANGES