


Optional probes and LH-600 calibration block


12AAF666

Ball probe $\varnothing$ 1 mm




12AAF670

Disk probe $\varnothing$ 5 mm




12AAC072 Depth measurement probe




957261

Ball probe $\varnothing$ 2 mm





12AAF671

Disk probe $\varnothing$ 10 mm




12AAF667

Ruby ball probe
 $\varnothing$ 2 mm




957264

Disk probe $\varnothing$ 14 mm




12AAC073 Tapered probe $\varnothing$ 20 mm




957262

Ball probe $\varnothing$ 3 mm




957265

Disk probe $\varnothing$ 20 mm



957263


Ball probe $\varnothing$ 4 mm




12AAF672

Ball offset probe*
 $\varnothing$ 1 mm

*Lever gage probe tip (103017)




12AAA792 Gage holder ($\varnothing$ 8 mm shaft)




12AAB552

Ball probe, L=55
 $\varnothing$ 10 mm



12AAF673


Ball offset probe
 $\varnothing$ 2 mm



12AAF668


Ball probe, L=82 $\varnothing$ 10 mm

10 ball-shaped and tungsten carbide-tipped contact point



12AAA788


Ball offset probe
 $\varnothing$ 4 mm



12AAF669


Ball probe, L=120 $\varnothing$ 10 mm

10 ball-shaped and tungsten carbide-tipped contact point...




12AAA789

Ball offset probe
 $\varnothing$ 6 mm




12AAA793 Probe extension holder (85 mm)




226116

Adapter for mounting probes
with $\varnothing$ 6 mm shaft



226117

Adapter for CMM
probe with M2 thread




932361


Holder for M μ checker

226118

Adapter for CMM
probe with M3 thread



12AAB136 $\varnothing$ 10 mm cylindrical probe with mount



12AAA787

Calibration block for probe diameters
(also suitable for tapered probes)